
AD-8526 Ethernet Converter Instruction Manual



A&D Company, Ltd.

The AD-8526 Ethernet Converter can connect the RS-232C interface of a weighing instrument to the Ethernet (LAN) port of a computer that is not equipped with an RS-232C interface. By using the AD-8526, weight data from a weighing instrument can be managed with a computer connected to the network. The weighing instrument can also be controlled by the connected computer.

Unpacking the AD-8526



If not specified, the following two communication cables are included:

DIN 7-pin to D-Sub 9-pin cable (AX-KO1786-200), D-Sub 9-pin to D-Sub 9-pin cable (AX-KO2466-200)

Specification

1. Specification		3. RS-232C serial interface		
Operating environment : -10°C to +40°C		Connector:	D-Sub 9-pin male	
AC adapter: Confirm that the adapter type is correct for		Transmission form: Asynchronous, bi-directional		
AC adapter: the lo	ocal voltage and power receptacle type		Baud rate:	600, 1200, 2400*, 4800, 9600, 19200bps
Power consumptio	n: Approx. 11VA (supplied to the AC adapter)	Data format	Data bits:	7* or 8 bits
Dimensions:	113(W) x 60(D) x 38(H) mm		Parity:	Even*, Odd, None
Net weight:	Approximately 250g		Stop bits:	1 bit* or 2 bits
2. Ethernet interface				
Connector:	RJ45		* : Factory	y settings
Protocol:	TCP/IP			

Weighing Instrument Cables

Required AD-8526 Cable by Weighing Instrument						
Weighing instrument	Interface option	Communications cable (Length 2 m)				
GX, GF, GX-K, GF-K, GP, GR, HR, MC	None (D-Sub 25-pin, standard accessory)	AX-KO1710-200				
EK-i, EW-i, FC-i, FC-Si, GH, HR-i	None (D-Sub 9-pin, standard accessory)	AX-KO2466-200				
AD-4212C	None (D-Sub 9-pin, standard accessory)	AD4212C standard accessory				
HV-G, HV-WP, HW-G, HW-WP	None (DIN 7-pin, standard accessory)	AX-KO1786-200				
FG	OP-03 (DIN 7-pin)	AX-KO1786-200				
FG-L, FG-M	OP-23 (DIN 8-pin)	AX-KO1786-200				

AFAA ALL IN MALL IN THE

Please refer to our website for the latest information.

Connecting the Weighing Instrument to a Computer

Caution

- Contact your network manager before connecting the AD-8526 to a network. The AD-8526 may generate a network error. A&D assumes no responsibility for any errors that may be caused.
- Affix the AC adapter labels to the AC adapter and the connector end of the cable.
- Set the IP address and subnet mask to the AD-8526 one at a time.
- The factory default IP address is 172.16.100.2. Do not duplicate an IP address.
- The IP address cannot be returned to the factory setting. We recommend that you write the IP address on the supplied label.

Preparation

Please download each software from A&D website

- (https://www.aandd.ip/products/software/software.html) for below. (1) Setting procedure "WinCT-Plus" instruction manual (2) IP address setting software "Device Installer" (3) Data acquisition software "WinCT-Plus"
- Step 1 Connect the AC adapter to the AD-8526.
- Step 2 Connect the AD-8526 and the computer with a cross cable directly or connect them with a hub and straight cables.
- Step 3 Input the IP addresses and subnet masks of the AD-8526 and computer. For the setting procedure, refer to the "WinCT-Plus" instruction manual.

Communication error may occur if set incorrectly.

- Step 4 Write the IP address on the IP address label and affix it on the AD-8526 (and the weighing instrument if necessary) where you can see the address easily.
- Step 5 Install the RsMulti data acquisition software to download the "WinCT-Plus" instruction manual.PDF form A&D website. (https://www.aandd.jp/products/software/software.html)
- Step 6 Connect the accessory RS-232C cable between the RS-232C interface of the weighing instrument and the AD-8526's port.

Data Communication Software


The RSMulti data acquisition software can be launched on a Windows PC. Menu: [Start] → [Program] → [A&D WinCT-Plus] → [RsMulti]. Refer to the Manual PDF file in the A&D WinCT-Plus for details on the operation.

- This software can acquire data from multiple devices connected by LAN or RS-232C.
- The software can control these devices with commands.
- The software can acquire data transmitted from devices. Example: When the PRINT key is pressed on the balance, data is output and is acquired with the computer.

Com


□ Stored data can be used with Excel. (Install Microsoft Excel before use.)

Example





tsMulti						
D Config() Copy() Excel()			New.csv			
ZND	05/04/12 11:23:16					
A&D Commenced implement	GX-600		GP-30K			
A&D Company,Limited	1 11:19:43	ST +0182.252	g 11:20:02 ST	+019218.1 g		
nual/Repeat	2 11:19:49	ST +0182.253	g 11:20:05 ST	+019218.2 g		
Repeat 5 sec	3 11:21:07	ST +0182.955	g 11:20:12 ST	+019218.2 g		
smand Data	4 11:21:12	ST +0182.964	g 11:20:39 ST	+019289.8 g		
A11	5 11:21:17	ST +0182.965	g 11:20:47 ST	+019218.2 g		
	6 11:21:33	ST +0186.676	g 11:23:02 ST	+019218.4 g		
est Start Cormand	7 11:21:41	ST +0182.251	g 11:23:09 ST	+019218.0 g		
	8 11:21:51	ST +0182.251	g 11:23:16 ST	+019218.0 g		
SX-600	9 11:22:00	ST +0182.965	9			
SP-30K	10 11:22:30	ST +0182.265	g			
JF-30K	11 11:22:33	ST +0182.252	g			
	12 11:22:40	ST +0182.239	g			
	_					



AC adapter

AD-8526

Step 2

